



The State of Utah

Department of
Natural Resources

Division of
Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:

Company	Dan Guy
Company	Boyd Rhodes
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070022
Inspection Type:	COMPLETE
Inspection Date:	Tuesday, October 19, 2004
Start Date/Time:	10/19/2004 10:00:00 AM
End Date/Time:	10/19/2004 3:00:00 PM
Last Inspection:	Tuesday, September 14, 2004

Inspector: Steve Demczak, Environmental Scientist III

Weather: Cold, 40's, Raining, Muddy

InspectionID Report Number: 434

Accepted by: pgrubaug
11/3/2004

Permittee: **SAVAGE SERVICES**

Operator: **SAVAGE SERVICES**

Site: **SAVAGE COAL TERMINAL**

Address: **6340 S 3000 E STE 600, SALT LAKE CITY UT 84121**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

160.00	Total Permitted
122.28	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☐ Federal
☐ State
☐ County
☐ Fee
☒ Other

Types of Operations

- ☒ Underground
☐ Surface
☒ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee has one permit condition. It is to enter the water monitoring data by using the Electronic Water Data System.

Inspector's Signature

Steve Demczak
Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date Wednesday, October 20, 2004

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
Where ideas connect™

Permit Number: C0070022
 Inspection Type: COMPLETE
 Inspection Date: Tuesday, October 19, 2004

Inspection Continuation Sheet

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permittee will be submitting an amendment to update officers and directors. In addition to the officers and directors update, the permittee will be submitting an amendment to build a maintenance and oil building for trucks.

2. Signs and Markers

Identification signs were inspected and comply with the R645 Coal Rules.

3. Topsoil

The topsoil pile was moved and re-seeded last year. No vegetation has been established. There are no signs of wind or water erosion to the topsoil pile. The upper topsoil has crusted over protecting the topsoil.

4.a Hydrologic Balance: Diversions

The diversions were functioning as designed. Water was flowing within the diversions.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected for the third quarter by the permittee. No hazardous conditions were reported. I inspected the sediment ponds and found no hazardous conditions. The sediment ponds did contain some water; since it has been raining for a few days.

4.d Hydrologic Balance: Water Monitoring

The permittee has submitted the third quarter water information for the second quarter.

4.e Hydrologic Balance: Effluent Limitations

There was no discharge for June and July.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected for the third quarter. No hazardous conditions were reported. I inspected the refuse pile and no hazardous conditions were noticed.

8. Noncoal Waste

The disturbed area was clear of non-coal waste material.

16.b Roads: Drainage Controls

Road drainage control was functioning as designed. Diversions along the roadways were collecting water and transporting the water into the sediment ponds.

18. Support Facilities, Utility Installations

There were no new support facilities added since the last inspection.

Permit Number: C0070022
Inspection Type: COMPLETE
Inspection Date: Tuesday, October 19, 2004

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

The insurance policy was inspected and complied with the R645 Coal Rules. This policy will expire on April 1, 2005.